



ASSEMBLY INSTRUCTION




ASSEMBLY INSTRUCTION


Part list:




A:1pc




B:1pc




C:2pcs




D:2pcs




E:2pcs




F:2pcs




G:2pcs




H:2pcs




I:2pcs



J:4pcs




K:4pcs




L:2pcs



M:1pc















N:1pc




O:1pc

ASSEMBLY INSTRUCTION


Hardware list:

 <p>M8*20 ①:36pcs</p>	 <p>M8*20 ②:2pcs</p>	 <p>M8*45 ③:2pcs</p>	 <p>M6*45 ④:12pcs</p>
 <p>65mm ⑤:8pcs</p>	 <p>M8 ⑥:38pcs</p>	 <p>M6 ⑦:12pcs</p>	 <p>⑧:1pc</p>
 <p>M8 ⑨:1pc</p>	 <p>M6 ⑩:1pc</p>	 <p>⑪:6pcs</p>	 <p>⑫:1pc</p>


Step:1



I*2




I*2




I*2


Please wait for 72 hours



H*2




H*2




H*2


Please wait for 72 hours



G*2



G*2





G*2

Please wait for 72 hours

Step:2

⑤ 8pcs



⑫ 1pc



Step:3

② 2pcs

⑨ 1pc




Step:4


③ 2pcs

⑥ 2pcs

⑨ 1pc



Step:5




Step:6

① 8pcs

⑥ 8pcs

⑪ 4pcs

⑨ 1pc




Step:7

④ 12pcs


⑦ 12pcs

⑩ 1pc




Step:8

- ① 8pcs
- ⑥ 8pcs
- ⑨ 1pc




Step:9

- ① 8pcs
- ⑥ 8pcs
- ⑨ 1pc




Step:10

- ① 8pcs
- ⑪ 2pcs
- ⑥ 8pcs
- ⑨ 1pc




Step:11


- ① 4pcs
- ⑥ 4pcs
- ⑨ 1pc



Step:12



Step:13



Step:14

