

























ASSEMBLY INSTRUCTIONS

1340057








Hardware

<p>A x 16</p>  <p>∅6 x 35 mm</p>	<p>B x 12</p>  <p>∅15 mm</p>	<p>C x 4</p>  <p>∅12 mm</p>	<p>D x 8</p>  <p>∅10 x 50 mm</p>
<p>E x 4</p>  <p>∅8 x 30 mm</p>	<p>F x 2</p>  <p>∅6 x 30 mm</p>	<p>G x 4</p>  <p>M 4 x 39 mm</p>	<p>H x 4</p>  <p>M 6 x 10.5 mm</p>
<p>I x 6</p>  <p>M 3.5 x 13 mm</p>	<p>J x 4</p> 	<p>K x 4</p> 	<p>L x 4</p>  <p>M 3.5 x 15.5 mm</p>
<p>RM30A x 1</p>  <p>300 mm</p>			


 <p>SET-UP TIME : 60 MINUTES</p>	 <p>NUMBER OF PERSONS : 02</p>	 <p>TOOLS : </p>
---	--	---


1





A	x 4	F	x 2
 Ø6 x 35 mm		 Ø6 x 30 mm	


2





C	x 4
 Ø12 mm	


3


G	x 4
	
M 4 x 39 mm	

4





I	x 6
	
M 3.5 x 13 mm	

K	x 4
	





L	x 4
	
M 3.5 x 15.5 mm	

RM30A	x 1
	
300 mm	


5





6





7




D	x 4	E	x 4
			
Ø10 x 50 mm		Ø8 x 30 mm	

8





B	x 4
	
Ø15 mm	




9





B





10





11



12



13



14

