

ASSEMBLY INSTRUCTIONS



Do not tighten screws until completely assembled.

PARTS INDENTIFICATION 1pc Α 2pcs D 4pcs Ε 2pcs В 3pcs HARDWARE LIST (a) 5pcs | M5x10 16pcs M5x10 M6x45 16pcs M4x37 4x4 1pc 1pc 2pcs 1pc 1pc



PAGE 2 OF 3

