





ASSEMBLY INSTRUCTIONS

Thank you for purchasing this quality product .Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.






Step 1:Please follow chart to assembly table leg B and table top A,Bt it don't tighten the long blot.

TOOLS REQUIRED(NOT PROVIDED):
PHILLIPS SCREWDRIVER 

PARTS LIST:

NO.	Description	Sketch	Quantity
1	Top		1 PC
2	Shelf		4 PCS
3	Leg		1 PC

HARDWARE LIST:

NO.	Description	Sketch	Size	Quantity
A	Long Blot		$\phi 1/4" * 1-1/2"$	8 PCS
B	Lock Washer		$\phi 1/4"$	8 PCS
C	Spring Washer		$\phi 1/4" * 16mm$	8 PCS
D	Allen Key		4mm	1 PC
E	Screw		$\#8 * 1-1/4"$	4 PCS

OTE: Straight Allen Key(k)is for use with a power drill.

