




I870001314A1




Tools required
(not included)



2 people for assembly

PRODUCT ASSEMBLY




Hardware List

A x54  6x35mm	B x54 	C x46  6x30mm	D x18  4x35mm	E x10 	F x60  4x14mm
G x47  3x14mm	H x36 	I x10  4x25mm	J x8 	K x5 	L x10  4x18mm
M x2 	N x22  4x12mm	O x2 	P x2 	Q x2 	R x25  4x35mm
S x3 	T x3 	U x6  4x12mm	V x36  3.5x12mm	W x5 	X x2 
CL x3 	CR x3 	DL x3 	DR x3 		

PRODUCT ASSEMBLY


Step 1



C x7	D x8	V x15	CL x3	CR x2	A x10	B x4

PRODUCT ASSEMBLY


Step 2



C x7	D x8	G x6	V x3	CR x1	A x14	B x4	S x3


PRODUCT ASSEMBLY

Step 3




PRODUCT ASSEMBLY

Step 4



B x4	C x4
	


Step 5



R x4	C x4
	


PRODUCT ASSEMBLY

Step 6



B x4	C x4
	


Step 7




R x4	C x4
	

PRODUCT ASSEMBLY

Step 8




Step 9




PRODUCT ASSEMBLY

Step 10




PRODUCT ASSEMBLY

Step 11




Step 12



PRODUCT ASSEMBLY


Step 13



K x5	L x10	W x5	G x5	E x10	F x60

PRODUCT ASSEMBLY

Step 14




T x1	U x2	V x6	A x5	B x5	DL x1	DR x1	R x5
							

PRODUCT ASSEMBLY

Step 16


x2




T x2	U x4	V x12	A x8	B x8	DL x2	DR x2	R x8

PRODUCT ASSEMBLY

Step 17



Step 18



N	x12	X	x2
			