











ASSEMBLY INSTRUCTION

Ax1 	Gx1 	① 		⑤ 
Bx1 	Hx5 	② 		⑥ 
Cx1 	Ix10  M6x12	③ 		
Dx1 	Jx12  M6x20	④  Attention : 1.screws should be only 50% tight. 2.after all the screws adjust the holes then tight screws 100% totally.		
Ex5 	Kx1 			
Fx1 				