



Assembly of Steel Bed

Read Before Beginning Assembly

Parts



8 x End Cup- (A)



4 x Screw (B)



8 x ss washer (C)



4 x ss Nut (D)




1/2 Wrench




3/16 AllenKey


1 x Headboard (E)



1 x Footboard (F)




2 x Side Rail (G)



1 x slats (H)





Step 1 – Insert end cups to Headboard and footboard (A x 8 in total)



Step 2 liftup headboard (E) and side rail,(G) align holes and insert screw(B) with one washer (c)on the head side . [see picture]. Add washer(c) and nut(D) and tighten using 1/2“ wrench and 3/16” Allen-key. Repeat on the right side.



Step 3 place slats (H) on side rail (G) and stretched them to the full length of the bed