
















Installation Manual























Installation Manual




Box 1/2:

 3 × 1pc	 4 × 1pc	 5 × 1pc	 6 × 1pc	
 7 × 1pc	 10 × 1pc	 11 × 1pc	 12 × 1pc	
 13 × 1pc	 21 × 12pcs	 26 × 1pc	 32 × 1pc	 G × 24pcs+2pcs


Box 2/2:

			
① × 1pc	② × 1pc	⑧ × 1pc	⑨ × 1pc
			
⑭ × 2pcs	⑮ × 2pcs	⑯ × 4pcs	⑰ × 2pcs
			
⑱ × 8pcs	⑲ × 2pcs	⑳ × 1pc	㉒ × 1pc
			
㉓ × 1pc	㉔ × 1pc	㉕ × 2pcs	㉗ × 2pcs
			
㉘ × 1pc	㉙ × 1pc	㉚ × 2pcs	㉛ × 2pcs

Box 2-1




Box 2-2












Box 2/2:

Box 2-3






Box 2-4







 M8×45mm Ⓐ ×8pcs+1pc	 M8×18mm Ⓑ ×84pcs+8pcs	 M6×40mm Ⓒ ×2pcs+1pc	 M6×20mm Ⓓ ×16pcs+1pc
 Ⓔ ×6pcs+1pc	 Ⓕ ×2pcs	 Ⓖ ×1pc	 Ⓖ ×1pc
 Ⓙ ×1pc			


1 Note: For easy setup intention,
do not tighten screws during
the installation process

 	 M8×18mm B × 8pcs
---	--





2

 	 M8×45mm A × 2pcs	 M8×18mm B × 8pcs	 E × 2pcs
--	---	--	---




3



M8×18mm




ⓑ × 4pcs





ⓕ × 2pcs

STEP1


STEP2





4




ⓔ × 2pcs







5

 	 M8×18mm B × 8pcs
---	--






6

 	 M8×45mm A × 4pcs	 M8×18mm B × 2pcs
--	---	---






7

 	 M6×20mm D × 8pcs
---	---



8


 	 M8×18mm B × 4pcs
--	---



9

70%






M8×18mm

B


 × 12pcs



10

70%








M8×18mm

B



 × 8pcs





11



12




13






M8×18mm

B × 4pcs




14




M8×45mm

A × 2pcs





M8×18mm

B × 4pcs




15






M8×18mm



B × 4pcs




16





32 × 1pc



17



70%




M6×40mm

C × 2pcs

x2



18




70%




19



20




M6×20mm
D × 4pcs



21

70%






M6×20mm

D


 × 4pcs



22

70%







M8×18mm

B

 × 4pcs




23




70%






M8×18mm

B × 2pcs




24



25

70%






M8×18mm


B


 × 4pcs



26

70%








M8×18mm

B


 × 4pcs






27




Ⓔ × 2pcs




28




Ⓕ × 1pc





29


G ×24pcs



30





Tighten all screws to 100% after inspection.

