

ASSEMBLY INSTRUCTIONS

PART & HARDWARE LIST IN HEADBOARD			STEP 1			STEP 2		
NO	PART & HARDWARE LIST IN HEADBOARD	QTY.						
A	HEADBOARD	1PC						
B	FOOTBOARD	1PC						
C	LEG (Marking L & R)	2PCS						
D	SLATS (3 HOLES)	4PCS						
E	BED SLAT SUPPORT	8PCS						
F	JCBC M6 X 30mm	6PCS						
E	SPRING WASHER $\text{\O} \frac{1}{4}$ "	6PCS						
G	FLAT WASHER $\text{\O} \frac{1}{4}$ " x 13mm	6PCS						
I	L KEY M4	1PC						