



WF315229
WF315230



ASSEMBLY INSTRUCTIONS




PARTS

Check that you've received
all parts listed below.


BOX: 1/2
WF315229

1 x 1




Head Board

4 x 1




Foot Board

8 x 4



Slats

9 x 6



Slats

10 x 4



Support Legs

PARTS

Check that you've received
all parts listed below.


BOX: 2/2
WF315230

2 x 1



Head Leg left

3 x 1



Head Leg Right

5 x 1




Side Board Left

6 x 1




Side Board Right

7 x 2




Legs

11 x 1



Support Slat











Hardware




HARDWARE


Check that you've received all hardware listed below.

Hardware List



| No. | OUTLOOK | DESC | QTY |
|-----|---|--------------------------------|-----|
| (A) |  | Bolts 5/16"x20 mm | 2 |
| (B) |  | Bolts 5/16"x30 mm | 8 |
| (C) |  | Bolts 5/16"x60 mm | 4 |
| (D) |  | Bolts 5/16"x70 mm | 8 |
| (E) |  | Plain washer Ø19x1.5 mm | 22 |
| (F) |  | Spring washer Ø13x1 mm | 22 |
| (G) |  | Allen key 80x30x4 mm | 1 |
| (H) |  | Screws Ø4x30 mm | 20 |
| (I) |  | Screws Ø4x15 mm | 8 |
| (K) |  | Dowel Ø10 x 30 mm | 4 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

STEP 1



| | | | | |
|--|--|--|--|--|
| K x 4  | | | | |
|--|--|--|--|--|





STEP 2





STEP 3





STEP 4





STEP 5





STEP 6



STEP 7




STEP 8





Tighten all screw bolts 100%

100%


STEP 9




100%





STEP 10





100%



STEP 11





STEP 12





Tighten all screw bolts 100%

100%

STEP 13



STEP 14



STEP 15

