





I870100972A1




**Tools required
(not included)**




2 people for assembly




1 x2




2 x1




3 x1




4 x2




5 x6




6 x2




7 x2



8 x1




9 x1




10 x2

PARTS



11 x4




12 x1

HARDWARE




ø22xM6x15

A x8




M6*10

B x16+2



M6*28

C x4+1




M6*50

D x32+2




E x2



435*180*2.0

F x2




400*298*2.0

G x3




H x2




S4

I x1




01



A x8


02




I x1




B x4





— **E** x2




 **G** x3

 **F** x2


05

**D** x20


06


**B** x4

07


**B** x1**C** x2**D** x6

08

**B** x1**C** x2**D** x6



B x6



H x2