












Diagram illustrating assembly instructions and warnings:





- Warning 1:** A box containing a crossed-out power drill icon and a warning triangle with an exclamation mark.
- Warning 2:** A box containing a crossed-out icon of a block being lifted by a person, a warning triangle with an exclamation mark, and a stick figure icon.
- Time:** A clock icon with the text "30'" below it, indicating a 30-minute assembly time.
- Personnel:** A stick figure icon with the number "2" below it, indicating that two people are required for assembly.






!






1






2






3






4






5



6



7



!

