


NOTE: Unbox and place all parts on a clean and smooth surface (rug, carpet) to avoid the parts from being scratched.

NOTE: Follow assembly instructions step by step.

NOTE: This bed comes in 3 boxes (4-5 if headboard is included)



HARDWARE LIST:


LABEL	PICTURE	DESCRIPTION	QTY	LABEL	PICTURE	DESCRIPTION	QTY	LABEL	PICTURE	DESCRIPTION	QTY
A	0	LONG BOLT	8	•	(9)	MEDIUM BOLT	8			SHORT BOLT	16
B		ALLEN WRENCH	1	D	0	FLAT WASHER	8	D			

ADDITIONAL HARDWARE LIST: (Hardware to attach headboard)


LABEL	PICTURE	DESCRIPTION	QTY	LABEL	PICTURE	DESCRIPTION	QTY
•	0	EXTRA LARGE BOLT	4	•	©	NUT	4
G	<u>S</u>	WRENCH	1	0	0	LRG FLAT WASHER	8

STEP 1: Attach two feet to both STEP 2: Next, screw on the support the backboard and the footlegs to the underside of each board using the 8- long bolts(A) drawer unit, 5 legs per unit and 8- washers(D). (see diagram) (See below diagram)


STEP 3: After the support legs are securely fastened, attach siderail to drawer cage using the 8 medium bolts(C).



STEP 4: Use bolts (E) to assembly Long Support Legs to Connecting Rods



STEP 5: With the drawer unit placed up right, standing on the support legs, attach the footboard and backboard and additional siderail using the hook attachments (please note: the attachment bolts on either end of the footboard and backboard can be loosened and tightened with the allen wrench FIG.1) Loosen the attachment bolts enough to fit the hooks in (FIG.1), aligning the side rails to the footboard and backboard, once all hooks are in place, tighten the attachment bolts, securing the four corners of the bed.(See below diagram)



STEP 6: Once all four corners are STEP 7: Lay the slats atop the bed securely tightened and Your bed is complete! connected, link drawer unit, (To attach a headboard: remove the slats siderail, footboard and backboard and align the horizontal slots on the backboard with the connecting rods with the vertical slots in the legs of your headboard. Once aligned, attach the two (see diagram). together using the additional bolts, washers, nuts (10)