


Assembly Instructions



Assembly
video



For any missing hardware, damaged parts and other problems.
WELCOME to email us at: **service@behousewell.com**

Or call at 1-833-474-1928 Toll free
Between 9AM and 5PM Eastern time, Monday through Friday

***Don't fully tighten all the bolts till the very end!**


PRE-ASSEMBLY PREPARATION:

- A cordless drill is recommended for ease of assembly.
- Clear out the space for assembly and lay out all of the parts based on the Parts List, extra room will allow you to easily determine if all the pieces are present.
- Keep small parts and pieces away from children until fully assembled.




A1

**Left
Arm
1pc**




C

**Left
Back
1pc**




F

**Right
Front
1pc**




A2

**Right
Arm
1pc**




D

**Left
Front
1pc**




G

**Support
Bar
1pc**




B

**Right
Back
1pc**




E







**Seat
Frame
1pc**





N,O,P

**Seat
Cushion
Back
Cushion**





No.	Part/Size	QTY	Image	No.	Part/Size	QTY	Image
H	Bolt (M6*15mm)	6	**Actural Scale 	M	Metal Plate	1	
I	Bolt (M6*20mm)	4	**Actural Scale 				
J	Bolt (M6*35mm)	14	**Actural Scale 				
K	Washer	24					
L	Allen Wrench	1					



Step 1 : Attach Left Back Frame C to Right Back Frame B with 2pcs bolts I and 2pcs washers K , using Allen Wrench L. Note:Don't fully tighten the bolts.





Step 2 :Attach Left Front Frame D to Right Front Frame F with 2pcs Bolts H and 2pcs Washers K , using Allen Wrench L. Note:Don't fully tighten the bolts.





Step 3 :Attach Left Arm A1 to Left Back Frame C with 2pcs Bolts H and 2pcs Washers K , using Allen Wrench L. Note:Don't fully tighten the bolts.




Step 4 : Attach Right Arm A2 to Right Back Frame B with 2pcs Bolts H and 2pcs Washers K , using Allen Wrench L. Note:Don't fully tighten the bolts.




Step 5: Attached Front Frame F & D to the Arm A1& A2 with 4pcs Bolts J and 4pcs Washers K, using Allen Wrench L. Note: Don't fully tighten the bolts.





Step 6 : Attach Support Bar G to Back Frame B & C with 2pcs bolts J and 2pcs washers K and Metal Plate M, using Allen Wrench L. Note: Don't fully tighten the bolts.





Step 7 : Attach Seat Frame E & Support Bar G to Front Frame D & F with 2pcs bolts I and 2pcs washers K , using Allen Wrench L. Note:Don't fully tighten the bolts




Step 8 :Attach Seat Frame E to Front Frame D & F with 2pcs bolts J and 2pcs washers K , using Allen Wrench L. Note:Don't fully tighten the bolts



Step 9 :Attach seat frame to Back Frame B & C with 6pcs bolts J and 6pcs washers K, using Allen Wrench L.



Step 10 : Turn up the sofa, put the Back Cushion P&O and Seat Cushion H to the sofa.



Q & A:

Q: Frame drilling holes not align?

A: If discrepancy less than 1/8 in., please loosen other relative bolts first, then adjust parts position and re-tight all bolts.

if discrepancy more than 1/4 in., it should be parts deformation during violent transportation, please contact us for parts replacement.

Q: Why cushion shrink packing and how to help it rebound faster?

A: We shrink packing cushion is to improve product value to cost, because it can save transport cost a lot. We filled it with more and high-quality filling than normal cushion to make sure it can be fully rebound. Following up this video(<https://youtu.be/IZAIHQU9IaI>)method to speed up rebounding.

Q: Coffee table legs un-even?

A: Loosen bolts, then press table downwards, then tighten bolts again. If it can not solve problem, please contact us for parts replacement.

Q: Wicker colors different on parts?

A: We make wicker stripes to fit for nature environment, colors may various circularly. So when those wicker stripes hand-woven on product randomly, it may looks different on parts.

Q: Why some swivel plate not work well?

A: Swivel plate may need a running-in period like 10~20 cycles. If it still not swivel well, please contact us for swivel plate replacement.

Q: Bolts are not long enough for assembly sometimes?

A: Sometimes gaps maybe larger than the bolts to reach out when assembly, please contact us for longer bolts. After all, those parts are woven by hand-made. But after it assembled and all bolts tightened, the gaps will be disappeared, because wicker parts are flexible surface.

Q: Parts received damaged?

A: Although we had already did our best to pack products well, there are also unpredictable transport damages accident happened from time to time. When it happens, please contact our after-sales email, state the order number/which shopping platform it comes from/one of the parcel tracking number, and provide the relevant pictures of the problem, we will immediately provide you with a suitable replacement parcel.

Q:Received item but missing hardware or parts

A:Please contact our after-sales email, state the order number/which shopping platform it comes from/one of the parcel tracking number, and provide the relevant pictures of the problem, we will immediately provide you with a suitable replacement parcel.