


Work bench with one drawer



1




- | | |
|-------------------|------------------|
| 1) M6x14 mm (x4) | 6) M6x10 mm (x7) |
| 2) M6x12 mm (x12) | 7) M6x10 mm |
| 3) M6x10 mm (x6) | 8) M6x12 |
| 4) M6x10 mm (x8) | 9) M6x10 |
| 5) 5x6 | 10) 5x6 |
| 6) M6x10 mm (x8) | 11) 10x10 |
| 7) M6x10 | 12) 5x6 |
| 8) M6x10 | 13) 5x6 |
| 9) M6x10 | 14) 5x6 |

2




- A(x1)
B(x1)
C(x1)

- D(x1)
E(x1)






3




- 21) 80mm (x2)
22) 99mm (x2)
23) (x1)
24) (x1)
25) (x1)
26) (x1)
27) (x1)
28) (x1)


4




5



4)




5)




6)


6



7)




8)




9)


7



10)




11)




12)


8



13)




14)




15)


9



16)




17)



18)

10



11