



























X2



K 32PCS	L Ø3.5*14mm 64PCS	M Ø3.5*25mm 4PCS	N Ø3.5*35mm 8PCS	O 2PCS	P 466mm 1PCS	Q Ø6*25mm 8PCS	R 350mm 2PCS	S 350mm 2PCS	T 350mm 2PCS
A 32PCS	B 32PCS	C Ø8*40mm 12PCS	D 6PCS	E 128mm 4PCS	F Ø4*25mm 8PCS	G G1 2PCS G2 2PCS	H 1PCS	I 40PCS	J 12PCS


1	964*473	2	964*473	3	1800*473	4	1800*473
	1PCS		1PCS		1PCS		1PCS
5	1706.5*473	6	472*470	7	473*473	8	1740*497
	1PCS		3PCS		1PCS		1PCS
9	1242*497	10	247*497	11	964*57	12	471*60
	1PCS		2PCS		2PCS		2PCS
13	350*150	14	350*150	15	449*150	16	341*404
	2PCS		2PCS		2PCS		2PCS
17	393*150	18	1740*497				
	2PCS		2PCS				




Hardware installation demonstration

NOTE: Please make sure "A" hardware tightened and can't be pulled out!


I




II





III



1




2



A*2



C*4



L*10



O*1




R*2




S*2

Put A on board ⑤


Put C on board ⑤



3



4 Make sure the arrow on the screw align to the hole on the side




B*4

Put B on board 11

5

Make sure the arrow on the screw align to the hole on the side




B*2

Put B on board ⑤

6

Make sure the arrow on the screw align to the hole on the side




B*2

Put B on board ⑤

7

Make sure the arrow on the screw align to the hole on the side




B*2

Put B on board ⑦

8


Make sure the arrow on the screw align to the hole on the side



B*8


Put B on board ①②⑦⑪

9




I*40







10





J*12


Put J on board ③④⑤






	F*4
	A*8
	E*2
	Q*8



	B*8
	L*8
	N*8
	U*2
	T*2





Put B on board ⑬⑭

X2







	D*6
	E*2
	F*4
	G1*2
	L*16

15




L*12


16



L*12



H*1



K*32

END