








JA25214

ASSEMBLY INSTRUCTIONS







+Spare X 2	
A	x 14
	
M8*18mm	


+Spare X 2	
B	x 18
	
M8*15mm	

+Spare X 1	
C	x 5
	
M6*15mm	


+Spare X 2	
D	x 26
	
Ø16*1.5mm	

+Spare X 2	
E	x 26
	
M8	


+Spare X 2	
F	x 18
	
4*14mm	

G	x 4
	

H	x 4
	

I	x 4
	
40*40*20mm	


J	x 2
	
30*30*20mm	

K	x 1
	
5mm	

L	x 1
	
4mm	



M	x 1
	

+Spare X 1	
N	x 9
	


+Spare X 1	
O	x 5
	
M8*25mm	

P	x 2
	
400x60x3mm	

Q	x 1
	
400x18x3mm	




3




B	x8	D	x8	E	x8	K	x1
							
M8*15mm		Ø16*1.5mm		M8		5mm	

4




K	x1	B	x8
			
5mm		M8*15mm	


5




6




7




8



9



10



11

