
Assembly Instructions



General Assembly Guidelines

- I. Ensure that all parts and hardware are available before beginning assembly.
- ||. Follow each step carefully to ensure the proper assembly of this product.
- III. Two people are recommended for ease in the assembly of this product.
- IV. The three main types of hardware used to assemble this product are : wood dowels , screws and bolts.
- V. The provided glue is to secure wood dowels in place. When first inserting dowels, locate the appropriate hole for the dowel, place a small amount of glue in the hole and insert the dowel. Wipe away excess glue immediately.




In future assembly steps when dowels are necessary to attach assembly parts together, place a small amount of glue on the end of the dowel before attaching parts together. Wipe away excess glue immediately.




M. A Phillips head screwdriver is required for the assembly of this product.




MI. Power tools should not be used to assemble this product.






Hardware List

Α		Ø8x30mm	Wooden dowel	36	pcs
В		Ø6x32mm	Cam bolt	60	pcs
С	\mathfrak{P}	Ø15x11mm	Cam lock	43	pcs
D		Ø15x9mm	Cam lock	17	pcs
Е		Ø30mm	Sticker	60	pcs
F		M 4	Hex Key	1	рс
G		M6*35mm	Bolt	2	pcs
Н		Ø4x32mm	Screw	17	pcs
I	₹		Handle	4	pcs
J		Ø4x9mm	Bolt	8	pcs
K		12"	Drawer slides	4	pcs
L		Ø3x12mm	Screw	48	pcs
М		Ø6	Iron Hanger	2	pcs
N			Plastic wedge	4	pcs
0		Ø3x17mm	Screw	4	pcs
Р			Glue tube	2	рс





The hardware quantities listed above are required for proper assembly.


Some extra hardware may also have been included.





Step 2 В В В В в В Вв В Вв ВВ 10 2 В X31















Put slider bracket into slider arm as per diagram.











Step 11 2 K X3 X1






























D X8


Step 22 25 J 26 J I m(}) X4 X2


Step 23 20 19 Н X5


Step 24 21 17 20 0.0 18






















Step 31 10 J I


X1


X2


Step 32 **°** 10 29 M M
















Step 38 *°* ⁄ E E E E E 2 Ε X13





Step 41 Slider bracket - J