



Bench




ASSEMBLY INSTRUCTIONS


A : 1 Pcs




B : 4 Pcs




C : 8 Pcs
Hexagonal Nut
m10





D : 8 Pcs
washer m10



1



2



No power tools; use supplied assembly tools only