




Changing table



NA028








Please prepare the following tools



When installing, please carefully confirm whether each screw corresponds to the manual, accessories with similar shapes can be distinguished by size

A x 56




B x 56




Ø15 x 9.5 mm

C x 36



Ø6 x 30 mm

D x 35



Ø5 x 40 mm

E x 48




Ø3.5 x 12 mm

F x 4




CL+CR+DL+DR x4

G x 4



H x 8



I x 16



I-1



I-2

J x 2



J-1



J-2



J-3



J-4

K x 4



L x 4



M4 x 8 mm


M x 56




Ø21 mm

Hardware


PARTS LIST




① x4




② x4




③ x4




④ x4




⑤ x4




⑥ x4




⑦




⑧




⑨




⑩




⑪




⑫




⑬



⑭ x2




⑮




⑯


PARTS LIST




17




18




19



20 x2




21




22 x2


1

D x 20




Ø5 x40 mm











2



X4

3

A x 20






X4

4

B x 20







X4

5



K x 4





L x 4




M4 x 8 mm





6




E x 24 	F DR+DL x 4 	
---	--	--






7








8

A x 8 	E x 12 	F CL x 4 		 
--	---	---	--	--










9


A x 8 	E x 12 	F CR x 4 	
--	---	---	--



10

B x 2 	C x 2 	
--	--	--











11


B x 4



C x 4




C



B


12

C x 10





Ø6 x30 mm


D x 13



Ø5 x40 mm






13



14

B x 8











15

B x 2



C x 2











16

B x 6



C x 4











17

B x 2



C x 2












18

B x 6



C x 4







B

C

19

H x 8













21

B x 6







C x 6






22

G x 4









23

I x 16		 
I-1	I-2	






24

J x 2



25



26

M x 56



Ø21 mm

