













JA20514 ASSEMBLY INSTRUCTION






A	x 26+1	B	x 8+1	C	x 30+1	D	x 4	E	x 8+1	F	x 4+1
											
M6x50		M6x30		M6x12		M8: Ø30X15		Ø18XØ8X1.5		Ø8X30	
G	x 1										
											
M4											


① x2pcs




② x2pcs




③ x4pcs




④ x2pcs




⑤ x2pcs




⑥ x3pcs



1




F	x 4
---	-----




∅8X30


2



C	x 6	G	x 1
---	-----	---	-----






M6x12




M4



3




C	x 4	G	x 1
			
M6x12		M4	



4




C	x 4	G	x 1
			
M6x12		M4	






5




B	x 8	G	x 1
			
M6x30		M4	



6



A	x 8	C	x 16	D	x 4	E	x 8	G	x 1
									
M6x50		M6x12		M8: 30X15		Ø18XØ8X1.5		M4	

7



A	x 18	G	x 1
			
M6x50		M4	

8

