


SKU: HY036-ZM


ASSEMBLY INSTRUCTIONS

A




A x 1


B



B x 1




C3




C3 x 1

D3




D3 x 1

E3




E3 x 1

H




H x 3

F3




F3 x 1

I




I x 3


G3




G3 x 1

No	Hardware	Fig	Q.ty
----	----------	-----	------


1	SCEW M6 x 40mm		2
---	----------------	---	---


2	SCEW M7x50mm		4
---	--------------	---	---

3	BOLT M6x35mm		4
---	--------------	---	---


4	BOLT M6x65mm		6
---	--------------	---	---

5	SCEW M4x35mm		2
---	--------------	---	---



6	SCEW M4x55mm		2
---	--------------	---	---

7	Allen key		2
---	-----------	---	---



Step 1




Step 2




Step 3





Step 4




Step 5



Step 6



Adjust height for balance



Adjust low for balance