





Assembly Instructions




HARDWARE LIST



A x 1pc




B x 2pcs



C x 1pc




D x 1pc




E x 1pc




F x 1pc




H x 6pcs




J x 1pc




K x 1pc



L x 1pc



M x 1pc



N x 1pc


PARTA LIST

①x 36pcs



M5 x 40mm

②x 4pcs




③x 8pcs



M4 x 12mm

④x 1pc




M4 x 12mm

⑤x 6 pcs




Ø6 x 30mm

⑥x 1pc



M4x40mm
M3x14mm





M3



STEP 1

Pay attention to the orientation of the guide hole



H x 6pcs
① x 10pcs



① x 10pcs

STEP 2


Pay attention to the orientation of the guide hole



① x 4pcs


E x 1pc
J x 1pc
① x 4pcs

STEP 3



K x 1pc
L x 1pc
M x 1pc
① x 8pcs
⑤ x 4pcs


STEP 4



② x 4pcs
③ x 8pcs


STEP 5

① x 1pc
D x 1pc




STEP 6

A x 1pc
① x 3 pcs
⑤ x 2 pcs




STEP 7



B x 2pc
F x 1pc
1 x 2pcs


STEP 8



C x 1pc
1 x 4pcs

STEP 9


① x4pcs




STEP 10

N x 1pc


④ x 1pc



STEP 11



STEP 12



6 x 1pc