




BOX 1-3 **4** x01




5 x04




6 x01



7 x08




10 x21




Instruction Hardware Kit


BOX &-' **1** x04




BOX '-3 **2** x04




3 x04




8 x08




9 x08




PARTS



HARDWARE



A x16
Φ6*55




B x48
Φ3.5*50





C x32
Φ3.5*35




D x08



G x08



A x16
Φ6*55





B x24
Φ3.5*50








C x32
Φ3.5*35



D x08






B x24
Φ 3.5*50



C x64
Φ 3.5*35



D x16




8

9

X8


B x96
Φ 3.5*50



C x08
Φ 3.5*35



F x04



E x04

