

完成

WUXT00874404.pdf



TEST REPORT

Number : WUXT00874404

Tests Conducted (As Requested By The Applicant)

1 Fibre Shedding (In-House Test Method 026):

Test Procedure :

- (1) Remove Loose Fibre/Tufts From The Cut Edges Of The Specimen (80 mm X 130 mm With The Longer Parallel To Pile Layer)
- (2) Cut A 200 mm Strip Of Pressure Sensitive Tape, Fold Over 25 mm At Each End Of The Tape And Weight As (A).
- (3) Apply The Tape To The Surface Centrally Along The Specimen And Place The Glass Plate And Loading On Top Leave For One Minute Under A Load Of 1 kg.
- (4) After One Minute, Remove The Weight And Pull The Tape Off Against The Lay Of The Pile.
- (5) Weight The Tape Plus Fibre As (B).
- (6) Weight Of Fibre Removed : (B)-(A).

Requirement

| | |
|------------------------------------|---------|
| The Photographic Assessment | Grade 4 |
| The Weight Of Fibre Removed | 0.9 mg |
| The Approximate Length Of The Pile | 11 mm |

Remark :
 Grade 5 : None
 Grade 4 : Slight
 Grade 3 : Moderate
 Grade 2 : Severe
 Grade 1 : Very Severe