










Warning icons and assembly instructions:

- 
- 
- 
- 
- 15'
- 
- 
- 
- 
- 2





C x 3




A

B





D x 4






D x 4




E



!



1




2

D




x 4

F




x 4

G





M8
x
60
x 4

H




x 1



3

A




x 1

D




x 4

F




x 4

G





M8
x
60
x 4


H



x 1



4



5

