




Diagram illustrating assembly instructions and safety warnings:


- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a rectangular block being placed on a surface and a diagram of a block with a hole and a slash through it, indicating a specific assembly or safety instruction.
- Time:** A clock icon is shown next to the text "40'", indicating a 40-minute assembly time.
- Person:** An icon of a person is shown next to the number "1", indicating that one person is required for assembly.





1 x 1



2 x 4



1



2

