



IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

ASSEMBLY & INSTRUCTION MANUAL


① x 1




② x 1




③ x 1




④ x 2




⑤ x 4




⑥ x 2




⑦ x 1




⑧ x 1




⑨ x 1




⑩ x 1




⑪ x 3

















⑫ x 2









HARDWARE



<p>A x22</p>  <p>M6*34</p>	<p>B x22</p>  <p>M15*12</p>	<p>C x14</p>  <p>M6*30</p>	<p>D x 4</p> 
<p>E x 4</p> 	<p>F x20</p>  <p>M3.5*14</p>	<p>G x16</p> 	<p>H x 4</p> 
<p>I x 4</p>  <p>M6*18</p>	<p>J x 2</p> 	<p>P x 1</p> 	

A		6 PCS
C		4 PCS
D		4 PCS






A		6 PCS
C		4 PCS




A		10PCS
C		6 PCS

03




J		2 PCS
F		12PCS

04




B  3 PCS



05



B  3 PCS


06






F 8 PCS

09




B 4 PCS

10




B  4 PCS

11




B  6 PCS


12




D  4 PCS



13




G  16 PCS

14



E		4 PCS
I		4 PCS

15



16

