



INSTRUCTION






Console Table

Caution: Read owner's manual completely before assembly and use.










Parts :

	PARTS	Q'TY
1		01
2		02
3		01
4		02
5		02


Hardware:

	HARDWARE	Q'TY
A	 $\varnothing 8 \times 30$	12
B	 D15	16
C	 D15	16
D	 M6 $\times$ 55	04
E	 M3.5 $\times$ 30	01
F	 M3.5 $\times$ 50	06
G	 M3.5 $\times$ 15	01
H		01
I		01
J	 D4	01

	SPARE HARDWARE	Q'TY
A	 $\varnothing 8 \times 30$	02
B	 D15	02
C	 D15	02
D	 M3.5 $\times$ 50	01


Step By Step Assembly Instructions

Step 1 :




Step By Step Assembly Instructions

Step 2 :




Step 3 :




Step By Step Assembly Instructions

Step 4 :



Step 5 :



Step By Step Assembly Instructions

Step 6 :

