
WF322139 WF322140



ASSEMBLY INSTRUCTIONS



PARTS | check that you've received all parts listed below

BOX:1/2 WF322139

(1PC)	② (1PC)
(12) (6PCS)	①1) (4PCS)
•	· · · · · · · · · · · · · · · · · · ·
(4) (1PCS)	(5) (1PC)
[D 0]	(o
8 (2PCS)	9 (2PCS)
10(2PCS)	14 (4PCS)
	HARDWARE
	The state of the s

PARTS | check that you've received all parts listed below


BOX:2/2 WF322140


③ (2PCS)	13 (1PC)
	• •


HARDWARE | check that you've received all parts listed below


Hardware List

NO	OUTLOOK	DESC	QTY
Α		Bolts Ø \$ 6" x 20 mm	14 pcs
В		Bolts Ø 76" x 50 mm	16 pcs
С		Plain washer Ø19x1.5 mm	30 pcs
D		Spring washer Ø13x1 mm	30 pcs
E		Allen key 80x30x4 mm	1 pc
F	A bengangangan	Screws Ø4x30 mm	26 pcs






















finish

