









ASSEMBLY INSTRUCTION




PARTS LIST


					
A	B	C	D	E	F
X1	X1	X1	X1	X1	X1
					
G					
X1					

HARDWARE LIST


	
1	X6




Step1




Step2




Step3




Step4





Step5




Step6



Step7



ASSEMBLY INSTRUCTION




PARTS LIST



A

X1



B

X1



C

X1



D



X1

HARDWARE LIST




1


X4




Step 1




Step2





Step3




Step4










Step5



ASSEMBLY INSTRUCTION




PARTS LIST


					
A X1	B X1	C X1	D X1	E X1	F X1
					
G X1					

HARDWARE LIST


	
1 X6	




Step1




Step2




Step3




Step4





Step5




Step6



Step7



ASSEMBLY INSTRUCTION



PARTS LIST



A

X1



B


X1

HARDWARE LIST




1


X4




Step 1









Step2



ASSEMBLY INSTRUCTION




PARTS LIST


					
A	B	C	D	E	F
X1	X1	X1	X1	X1	X1

HARDWARE LIST


 Ø 55X30mm	
1	G
X4	X2




Step1




Step2




Step3



Step4



Step5



Step6

