










Ax2 	Cx1 	Fx1  $\frac{4}{0.2}$		
Bx2 	Dx1 	Gx8  $\frac{16 \times 3.5}{0.6 \times 0.1}$		
	Ex12  $\frac{25 \times 6}{1.0 \times 0.2}$	Hx1 		
 A+B+E+F			 A+B+C	 A+B+C
 A+B+C+E+F		 A		

D

$\frac{\text{mm}}{\text{inch}}$
x2

