










AL 1 PC	AR 1 PC	B 1 PC	C 1 PC	D 1 PC	E 2 PCS
					
M6*12	M8*35	M6	M8		
F 10PCS	G 4 PCS	H 10 PCS	I 4 PCS	J 4 PCS	K 4 PCS
					
M6	M8				
L 1 PC	M 2 PCS				


①










②




③




<p>A</p>	 <p>x 1</p>	<p>E</p>	<p>M6*25</p>  <p>x 8</p>
<p>B</p>	 <p>x 4</p>	<p>F</p>	 <p>x 16</p>
<p>C</p>	 <p>x 1</p>	<p>G</p>	 <p>x 1</p>
<p>D</p>	<p>M6*15</p>  <p>x 8</p>		

①



②



③

