




PARTS LIST




A x1



B x1




C x2



D x2



E x2



F x6



G x4





H x24+1





J x24+1

Step 1





Hx8

Step 2





Hx8

Step 3




Hx8

Step 4



Jx24

Step 5



COMPLETION

