






















**Do not firmly tighten the screws 100% until the item is completely assembled.**


	 <p><b>A x 1</b></p>	 <p><b>B x 8</b></p>	 <p><b>C x 2</b></p>	 <p><b>D x 1</b></p>
 <p><b>x 1</b></p>	 <p><b>E x 1</b></p>	 <p><b>F x 2</b></p>	 <p><b>I x 2</b></p>	 <p><b>J x 4</b></p>
	 <p><b>K x 1</b></p>	 <p><b>L x 1</b></p>		
 <p><b>x 1</b></p>	 <p><b>G x 1</b></p>	 <p><b>H x 4</b></p>		
 <p><b>M6x20 AA x 40</b></p>	 <p><b>M6x60 BB x 2</b></p>	 <p><b>CC x 1</b></p>	 <p><b>DD x 1</b></p>	




1





50%




2





3




50%





4




50%





5




50%




6





100%




7





8




50%




9




100%




10





11








1




50%



2



100%



3

