



# BED FRAME



Thank you for choosing our products, please assemble and use it following the instructions.

# Assembly Instruction







## Important Note

### HARDWARE NOTE :

1. Two or more people are required for assembly
2. Do not screw on the bolts too tight unless the installation is done. Make sure all bolts are tightly screwed before you use it.

# Components



M8x16 • • • • • • • • • • **A** x11pcs

M8x25 • • • • • • • • • • **B** x24pcs

M8x30  
white zinc • • • • • • • • • • **C** x8pcs

M8x35 • • • • • • • • • • **D** x19pcs

M8x55 • • • • • • • • • • **E** x54pcs

M5x40 • • • • • • • • • • **F** x9pcs

ST4x14 • • • • • • • • • • **G** x2pcs

M8 • • • • • • • • • • **H** x2pcs

• • • • • • • • • • **I** x48pcs

M8 • • • • • • • • • • **J** x1pc

M5 • • • • • • • • • • **K** x1pc


• • • • • • • • • • **L** x1pc

• • • • • • • • • • **U** x1pc


• • • • • • • • • • **Y** x2pcs

• • • • • • • • • • **Z** x2pcs


TYPE 1



TYPE 2




TYPE 1



1


x2



|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| D |  | 4pcs |
|---|------------------------------------------------------------------------------------|------|


2

x2



|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| B |   | 4pcs |
| E |  | 4pcs |


3



 Do not fully tighten the screws yet.

|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|


4



 Do not fully tighten the screws yet.

|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 6pcs |
|---|-------------------------------------------------------------------------------------|------|


5



**!** Do not fully tighten the screws yet.

|   |                                                                                          |      |
|---|------------------------------------------------------------------------------------------|------|
| A |  M8x16  | 3pcs |
| D |  M8x35 | 3pcs |


6



**!** Do not fully tighten the screws yet.

|   |                                                                                           |      |
|---|-------------------------------------------------------------------------------------------|------|
| A |  M8x16 | 2pcs |
|---|-------------------------------------------------------------------------------------------|------|


7



|   |                                                                                           |     |
|---|-------------------------------------------------------------------------------------------|-----|
| D |  M8x35 | 1pc |
| E |  M8x55 | 1pc |

8


x5



|   |                                                                                           |       |
|---|-------------------------------------------------------------------------------------------|-------|
| B |  M8x25 | 10pcs |
|---|-------------------------------------------------------------------------------------------|-------|


9

x2



|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| B |   | 8pcs |
| E |  | 8pcs |


10



|   |                                                                                    |       |
|---|------------------------------------------------------------------------------------|-------|
| E |  | 12pcs |
|---|------------------------------------------------------------------------------------|-------|


 Fully tighten all the screws.

11




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| B |  | 2pcs |
| E |  | 2pcs |

12




|   |                                                                                     |     |
|---|-------------------------------------------------------------------------------------|-----|
| E |  | 1pc |
|---|-------------------------------------------------------------------------------------|-----|

13



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| A |  | 4pcs |
|   | M8x16                                                                               |      |


14



|   |                                                                                      |      |
|---|--------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|   | M8x55                                                                                |      |

**!** Do not fully tighten the screws yet.


15



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|   | M8x55                                                                               |      |


**!** Do not fully tighten the screws yet.

16




|   |                                                                                      |      |
|---|--------------------------------------------------------------------------------------|------|
| E |  | 2pcs |
|   | M8x55                                                                                |      |
| H |  | 2pcs |

17



|   |                                                                                    |       |      |
|---|------------------------------------------------------------------------------------|-------|------|
| D |  | M8x35 | 4pcs |
|---|------------------------------------------------------------------------------------|-------|------|


18



|   |                                                                                    |       |      |
|---|------------------------------------------------------------------------------------|-------|------|
| E |  | M8x55 | 2pcs |
|---|------------------------------------------------------------------------------------|-------|------|


 Do not fully tighten the screws yet.

19



|   |                                                                                     |       |      |
|---|-------------------------------------------------------------------------------------|-------|------|
| E |  | M8x55 | 2pcs |
|---|-------------------------------------------------------------------------------------|-------|------|


20



|   |                                                                                     |       |      |
|---|-------------------------------------------------------------------------------------|-------|------|
| D |  | M8x35 | 4pcs |
|---|-------------------------------------------------------------------------------------|-------|------|

 Do not fully tighten the screws yet.

21




|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| C |  | 4pcs |
|---|------------------------------------------------------------------------------------|------|

M8x30

**!** Do not fully tighten the screws yet.

22



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| A |   | 1pc  |
| D |  | 2pcs |


M8x16

M8x35

A

D

23




|   |                                                                                     |     |
|---|-------------------------------------------------------------------------------------|-----|
| A |  | 1pc |
| D |  | 1pc |

M8x16

M8x35

**!** Do not fully tighten the screws yet.

24




|   |                                                                                      |      |
|---|--------------------------------------------------------------------------------------|------|
| E |  | 2pcs |
|---|--------------------------------------------------------------------------------------|------|

M8x55

**!** Do not fully tighten the screws yet.


25



|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| F |  | 6pcs |
|---|------------------------------------------------------------------------------------|------|

M5x40


26



|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| F |  | 3pcs |
|---|------------------------------------------------------------------------------------|------|

M5x40

27




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| C |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|

M8x30

 Fully tighten all the screws.



28



|   |                                                                                      |      |
|---|--------------------------------------------------------------------------------------|------|
| G |  | 2pcs |
|---|--------------------------------------------------------------------------------------|------|



ST4x14

29




30

- 1: Using a drill bit with a diameter of 6, drill mounting holes where installation is required
- 2: Place the expansion tube into the hole
- 3: Screw the screw together with the mounting part into the expansion pipe




# Finish

31




Note: Now you can tighten all the bolts.

TYPE 2




1  
x2




|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| D |  | 4pcs |
|---|------------------------------------------------------------------------------------|------|

2  
x2



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| B |  | 4pcs |
| E |  | 4pcs |


3




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|

 Do not fully tighten the screws yet.

4



Note:  
Hole position




E

|       |                                                                                    |      |
|-------|------------------------------------------------------------------------------------|------|
| E     |  | 6pcs |
| M8x55 |                                                                                    |      |

 Do not fully tighten the screws yet.

5




D

|       |                                                                                     |      |
|-------|-------------------------------------------------------------------------------------|------|
| A     |   | 3pcs |
| M8x16 |                                                                                     |      |
| D     |  | 3pcs |
| M8x35 |                                                                                     |      |

 Do not fully tighten the screws yet.

6




A

|       |                                                                                     |      |
|-------|-------------------------------------------------------------------------------------|------|
| A     |  | 2pcs |
| M8x16 |                                                                                     |      |

 Do not fully tighten the screws yet.

7




E

|       |                                                                                      |     |
|-------|--------------------------------------------------------------------------------------|-----|
| D     |  | 1pc |
| M8x35 |                                                                                      |     |
| E     |  | 1pc |
| M8x55 |                                                                                      |     |

8


x5



|   |                                                                                    |       |
|---|------------------------------------------------------------------------------------|-------|
| B |  | 10pcs |
|   | M8x25                                                                              |       |


9

x2



|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| B |   | 8pcs |
|   | M8x25                                                                              |      |
| E |  | 8pcs |
|   | M8x55                                                                              |      |


10



|   |                                                                                     |       |
|---|-------------------------------------------------------------------------------------|-------|
| E |  | 12pcs |
|   | M8x55                                                                               |       |


 Fully tighten all the screws.

11




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| B |  | 2pcs |
|   | M8x25                                                                               |      |
| E |  | 2pcs |
|   | M8x55                                                                               |      |

12




|       |                                                                                    |     |
|-------|------------------------------------------------------------------------------------|-----|
| E     |  | 1pc |
| M8x55 |                                                                                    |     |

13



|       |                                                                                     |      |
|-------|-------------------------------------------------------------------------------------|------|
| A     |  | 4pcs |
| M8x16 |                                                                                     |      |


14



|       |                                                                                     |      |
|-------|-------------------------------------------------------------------------------------|------|
| E     |  | 4pcs |
| M8x55 |                                                                                     |      |

**!** Do not fully tighten the screws yet.


15




|       |                                                                                      |      |
|-------|--------------------------------------------------------------------------------------|------|
| E     |  | 4pcs |
| M8x55 |                                                                                      |      |

**!** Do not fully tighten the screws yet.


16



17




18




 Do not fully tighten the screws yet.

19



20




|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| D |  | 4pcs |
|---|------------------------------------------------------------------------------------|------|

M8x35

⚠ Do not fully tighten the screws yet.

21




⚠ Do not fully tighten the screws yet.

|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| C |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|

M8x30

22




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| A |  | 1pc  |
| D |  | 2pcs |

M8x16

M8x35

18

23




⚠ Do not fully tighten the screws yet.

|   |                                                                                       |     |
|---|---------------------------------------------------------------------------------------|-----|
| A |  | 1pc |
| D |  | 1pc |

M8x16

M8x35

24




|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| E |  | 2pcs |
|---|------------------------------------------------------------------------------------|------|

M8x55

**!** Do not fully tighten the screws yet.


25



|   |                                                                                    |      |
|---|------------------------------------------------------------------------------------|------|
| F |  | 6pcs |
|---|------------------------------------------------------------------------------------|------|

M5x40


26



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| F |  | 3pcs |
|---|-------------------------------------------------------------------------------------|------|

M5x40

27




**!** Fully tighten all the screws.

|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| C |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|


M8x30

28



|   |                                                                                           |      |
|---|-------------------------------------------------------------------------------------------|------|
| G |  ST4x14 | 2pcs |
|---|-------------------------------------------------------------------------------------------|------|


29



|   |                                                                                     |       |
|---|-------------------------------------------------------------------------------------|-------|
| I |  | 48pcs |
|---|-------------------------------------------------------------------------------------|-------|

30

- 1: Using a drill bit with a diameter of 6, drill mounting holes where installation is required
- 2: Place the expansion tube into the hole
- 3: Screw the screw together with the mounting part into the expansion pipe



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| Z |  | 2pcs |
|---|-------------------------------------------------------------------------------------|------|

Finish

31



Note: Now you can tighten all the bolts.