




THEODORE ALEXANDER

TA54311

ASSEMBLY INSTRUCTION


Page: 1/3

P1 Top




x 1

P2 Base




x 1

P3 Leaf



x 1

P4 Center support



x 1

1 Steel allen bolt, lock, flat washer (Short)




x 8

2 Steel allen bolt, lock, flat washer (Long)





x 2

3 Steel allen wrench



x 1






THEODORE ALEXANDER

TA54311

ASSEMBLY INSTRUCTION


Page: 2/3




TA54311

ASSEMBLY INSTRUCTION


Sketch 1



Sketch 3



Sketch 2



Sketch 4

