


Bar Table

Assembly Instructions
Instrucciones De Asamblea
Instructions d'Assemblée

PARTS




A




B



C




D



6Vac 500 mA Adapter



E

1



remove black cap and throw away


2



LED Operation

1. Charge internal battery using Adaptor (E). Battery lasts 6 - 8 hours on a full 8 hour charge.
2. Push SPEED button to regulate color phasing between Slow, Medium and Fast.
3. Push ON/OFF button to turn LEDs on and off.
4. Push HOLD button to pause LEDs on specific color.

3



4

