




Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown next to a crossed-out power drill icon, indicating that power tools should not be used for assembly.
- Warning 2:** A warning triangle with an exclamation mark is shown next to a crossed-out icon of a block being lifted by a hand, indicating that the table should not be lifted by the top surface.
- Time:** A clock icon is shown next to the number "20'", indicating an estimated assembly time of 20 minutes.
- Personnel:** An icon of a person is shown next to the number "2", indicating that two people are required for assembly.



1 x 4

B





x 1

C




x 1





2


A



x 1



!



!

