







ASSEMBLY INSTRUCTIONS


 A M3.5*50 56PCS	 B M3.0*20 40PCS	 C M3.5*40 14PCS	 D M3.5*30 28PCS	 E M6.0*60 16PCS
 F M6.0*50 10PCS	 M3.0*16 12PCS G 3PCS	 H M8.0*75 4PCS	 J M8.0*60 2PCS	 K M3.5*35 8PCS
 L M3.5*60 8PCS	 M M3.5*20 4 PCS	 N 2PCS		




3




4




5




6




7




8




9




10




11 x2




15



16




17




18



24




25



26 x2



27 x2




28 x2




29 x2




30 x2




31 x8



32 x2




33




34 x4




37




38




39 x4




①




②




⑫x2



⑬



⑭



⑱x2



⑳x2



㉑




㉒



㉓




㉓x5



㉔x2


STEP 1

Jx1
Hx4




STEP 2

Ax16
Gx1




STEP 3

Ax20
Gx1




STEP 4

Ax10
Gx1




STEP 5


Ax10




STEP 6




STEP 7




STEP 8




STEP 9



STEP 10




STEP 11




STEP 12

Dx20




STEP 13


Jx1




STEP 14



STEP 15



STEP 16



STEP 17

