



Factory name



Factory gate



Production building



Cutting



Sewing



Polishing



Welding



Metal working



Powder coating



Weaving



Assembling



Packing



Drinking water



Suggestion box



Emergency exit sign, fire alarm and emergency lighting



Evacuation plan



Fire hydrant



Emergency lighting test



Fire alarm test



Fire hydrant test



Attendance record machine



Fire extinguishers



First aid kit



Toilet



Evacuation sign



amfori BSCI code



NC: Electrical box was not locked



NC: No needle guard



NC: No private door, tissue or soap



Nil