






Upholstered Bed/INSTRUCTION MANUAL



WF317595AAZ


PART LIST OF BED:

A	Headboard		1pc
B	Footboard		1pc
C	Side Rail		2pcs
D	Side Rail		2pcs
E	Slats		2pcs
F	Horizontal metal Support		1pc
F1	Side Rail Support leg		2pcs
H	Plastic Leg		4pcs

HARDWARE LIST OF BED:


1	Bolt		M8*25	2pcs
2	Allen Key		35*70*M5	1pc

1




2	Allen Key		35*70*M5	1pc
---	-----------	---	----------	-----

2




2	Allen Key		35*70*M5	1pc
---	-----------	---	----------	-----

3



2	Allen Key		35*70*M5	1pc
---	-----------	---	----------	-----


4



1	Bolt		M8*25	2pcs
2	Allen Key		35*70*M5	1pc

5

After the hanging piece is hung on the screw, tighten the screw clockwise to 100%.



2


Allen Key



35*70*M5

1pc

6



7

