























Assembly Instruction







1  1130x49x15 x1	2  1130x352x15 x1	3  959x353x15 x1	4  759x306x15 x3
5  760x306x15 x1	6  1137x265 x3	7  1130x59x15 x2	8  895x313x15 x1
9  354x306x15 x3	10  355x306x15 x1	11  959x353x15 x1	12  1162x354x15 x1
13  90x50x50 x4	14  888x373x15 x1	15  888x373x15 x2	16  60x40x87 x1


A  Φ6X35mm x 15+1	B  Φ15X10mm x 15+1	C  Φ6X30mm x 24+2	D  Φ5X40mm x 22+1	E  Φ3X12mm x 6
F  Φ3X14mm x 6	G  Φ21 x 6	H  H-1 Φ4X18mm x 3	I  Φ6X50mm x 2	J  45X12 x 3
K  45X16 x 3	L  Φ4X12mm x 4	M  M-1 Φ3X16mm x 12	N  5mm x 24+1	O  O-1 O-2 O-3 Φ4X12mm x 2
P  P-1 P-2 P-3 Φ4X45mm x 2	Q  Φ5 x 6			

1




A	F	K
		
x 3	x 6	x 3

2




A	N
	
x 8	x 12

3




A	N
	
x 4	x 12

4





E	H	J
	 H-1  H-2	
x 6	x 3	x 3

5




B	C
	
x 1	x 2

6




B	I
	
x 4	x 2


7




B	C
 x 2	 x 2


8




D
 x 2

9




B	C	D	G
			
x 4	x 7	x 3	x 3

10




11



B	C	D	G
			
x 4	x 7	x 3	x 3


12




D

x 8


13



14



15




Q



x 6

16



M



M-1



M-2

x 12

O

O-1



O-2

O-3



x 2

17



- P
- | | | |
|-----|-----|-----|
| P-1 | P-2 | P-3 |
| | | |
| x 2 | | |

18

