




Corner Floor Cabinet - Shutter Doors






Exploded Drawing



Product Parts

A




1 PC

B




1 PC

C




1 PC

D



1 PC

E




1 PC

F




1 PC

G



1 PC

H




1 PC

I




1 PC

J



1 PC

K



1 PC

! Care Instructions


Dust surface with a dry soft cloth.
Do not use window cleaners or cleaning abrasives as they will scratch the surface and could damage the protective coating

! WARNING

Small parts and sharp edges may be present prior to assembly.

Hardware


1



Ø8*30mm


28 PCS

2



20 PCS


3



Ø15*12

20 PCS


4



Ø4*25mm

3 PCS


5



Ø3*12mm


4 PCS

6



1 PC

7




1 PC

8



4 PCS


9



Ø4*25mm

4 PCS

10



2 PCS

11



2 PCS


12





4 PCS



Step 1

- 1**  **6 pcs** $\varnothing 8 \times 30 \text{ mm}$
2  **4 pcs**
3  **4 pcs** $\varnothing 15 \times 12$
4  **3 pcs** $\varnothing 4 \times 25 \text{ mm}$




Step 2

- 1**  12 pcs **2**  8 pcs
 Ø8*30mm



Step 3

- 1**  **4 pcs** $\varnothing 8 \times 30 \text{ mm}$
3  **8 pcs** $\varnothing 15 \times 12$



Step 4


1





Ø8*30mm

6 pcs




2



8 pcs



Step 5




Step 6

8



4 pcs



Step 7

- 9**  $\text{Ø}4 \times 25\text{mm}$ 4 pcs **10**  2 pcs **11**  2 pcs **12**  4 pcs

