






Ax1 	Bx2 	Cx2 	Dx2 	Jx4  M8	Kx1  12mm
Ex2 	Fx1 	Gx16  M6*30	Hx1  4mm	Ix16  1.5	Lx1  14mm


Step1






Step2




Step3




Ax1 	Bx2 	Cx2 	Dx2 	Jx4  M8	Kx1  12mm
Ex2 	Fx1 	Gx16  M6*30	Hx1  4mm	Ix16  1.5	Lx1  14mm

Step1



Step2



Step3

