




























ASSEMBLY INSTRUCTION






					
A x 16	B x 16	C x 24	Ø 4*40 D x 13	Ø 3*12 E x 42	F x 2
					
G x 2	H x 4	Ø 3*14 I x 14	J x 4	K x 1	Ø 4*30 L x 10
					
M x 8	N x 4	O x 10	P x 1	Q x 1	R x 1

			
① x 2	② x 2	③ x 2	④ x 2
			
⑤ x 2	⑥ x 1	⑦ x 1	⑧ x 1
			
⑨ x 1	⑩ x 1	⑪ x 1	⑫ x 2
			
⑬ x 1	⑭ x 1	⑮ x 1	⑯ x 1
			
⑰ x 1	⑱ x 1	⑲ x 2	⑳ x 2




step 1



	E x 12
	DL x 2
	DR x 2

X2



step 2



	L x 8
---	-------



X2

step 3





X2

step 4



X2

step 5



A x 4




E x 6



CL x 2

step 6





A x 4



G x 1



I x 2




E x 6





CR x 2

step 7





	B x 4
	C x 2
	G x 1
	I x 2


step 8




step 9



step 10



step 11





B x 4




C x 4


step 12





step 13




step 14




step 15





step 16



step 17



step 18



	K x 1
	Q x 1
	I x 10
	O x 10

step 19

