













Assembly Instructions



HARDWARE LIST


 A x 1pc	 B x 1pc	 C x 1pc
 D x 1pc	 E x 1pc	 F x 1pc
 G x 1pc	 H x 4pcs	 K x 1pc

PARTA LIST

 M5 x 40mm ①x 20pcs	 M3 ②x 1pc	 Ø5 x 35mm ③x 4pcs	 Ø15 x 10mm ④x 4pcs
 ⑤x 4pcs	 ⑥x 1pc	 M3 x 16mm ⑦x 4pcs	 M5 ⑧x 1pc


STEP 1

B x1pc
H x4pcs
①x8pcs
②x1pc




STEP 2

E x1pc
F x1pc
①x6pcs
②x1pc




STEP 3

A x1pc
③x4pcs
⑥x1pc




STEP 4




④x4pcs
⑧x1pc

STEP 5




C x1pc
①x4pcs
②x1pc

STEP 6




G x1pc

STEP 7



D x1pc
①x4pcs
②x1pc

STEP 8



K x1pc
⑤x4pcs

STEP 9

- | | |
|---|-------|
| 6 | x1pc |
| 7 | x4pcs |

