


PARTS

1 x 1




2 x 1



3 x 2




4 x 1



HARDWARE


A x 8
M6.0x35
+1(spare)



B x 8
+1(spare)



1 x 1



3 x 2




A x 4




M6.0 x 35

01



②x1




A x 4




M6.0 x 35



B x 8



A x 4



④x1



DONE