





Product Instruction






IMPORTANT INFORMATION!

please read the entire manual before starting to assemble and/or using this product. follow the manual thoroughly and keep it for further reference.





AVOID SCRATCHES!

In order to avoid scratching this furniture should be assembled on a soft layer—could be a rug.



IMPROVE EFFICIENCY !

Try to find a partner to install with you, which can speed up the installation efficiency and shorten the time.



ANTI-TOPPLE WARNING !


Overturned furniture can cause serious or fatal crush injuries. To prevent tipping over, be sure to use the wall attachment, if not included with this product. Please purchase the wall attachment that fit your wall. If unsure, seek professional advice. Please read and follow each step of the instructions carefully.


IMPORTANT !

It is important that any product which is assembled using any kind of screw is re-tightened 2 weeks after assembly, and once every 3 months - in order to assure stability through-out the lifespan of the product.


For regular maintenance and cleaning of the product, for the frame, please use a rag dipped in neutral detergent to fully wipe it, and then dry it with a clean rag. For glass materials, wipe with a rag dampened with water glass cleaner, and then dry with a dry rag.

Do not use an electric screwdriver, and do not use too much force when installing, because the board is easy to break.













Please prepare the following tools



When installing, please carefully confirm whether each screw corresponds to the manual, accessories with similar shapes can be distinguished by size



A x 70+5  Ø6 x35 mm	B x 16+1  Ø15 x 9,5 mm	C x 54+5  Ø15 x 11 mm	D x 26+2  Ø8 x 30 mm	E x 4  Ø6x30 mm
F x 4  CL CR DL DR L=350 mm	G x44+5  Ø3 x 12 mm	H x 2  L=450 mm	J x 24+2  Ø 3,5X14mm	K x 16+1  Ø 4x30mm
L x 5 	N x 12+2  Ø 3,5X14mm	M x 2 	P x 4 	Qx 1 
R x 1 	Sx 12+1 	T x 3  Ø 4x25mm	U. x 2  Ø 4x12mm	 Package of spare white nuts

1



x2

2






x4

3

C x 24



Ø15 x 11 mm






x2

4

A x 8



D x 8



x2

5

F x 1






L = 350 mm

G x 2



Ø3 x 12 mm






6

F x 1
L = 350 mm

G x 4
Ø 3 x 12 mm


Ax4
Ø 6 x 35 mm



7

C x 4



Ø15 x 11 mm




8

C x 4

Ø15 x 11 mm



9



10

F x 2



CR

L = 350 mm

G x 4



Ø 3 x 12 mm

H x 1



L = 450 mm

J. x 3







Ø 3,5 x 14 mm

Ax2



Ø 6 x 35 mm



11

A x 2



Ø6 x 35 mm

H x 1



L = 450 mm

J. x 3



Ø3,5 x 14 mm

F x 2








CL

L = 350 mm

G x 4



Ø3 x 12 mm



12

F x 1



CR


L = 350 mm

G x 2




Ø 3 x 12 mm

Ax2



Ø 6 x 35 mm




13

C x 4



Ø 15 x 11 mm





14


C x 4



Ø15 x 11 mm



15




16

C x 4




Ø15 x 11 mm



17

A x 10




Ø6 x 35 mm

D x 10



Ø8 x 30 mm





18

C x 10





Ø15 x 11 mm





19



P x 4



20



21





22

K x 12





Ø 4x30mm







x3

23



x2

24




25

B x 8



Ø 15 x 9,5 mm




x2

26

B x 4



Ø 15 x 9,5 mm



27

F x 2




L = 350 mm

G x 8



Ø3 x 12 mm



X2

28

F x 1




L = 350 mm


G x 4



Ø3 x 12 mm




29






x2

30




31





32


K x 4  Ø 4x30mm	E x 2  Ø 6 x 30 mm
--	---



33



34




35


B x 4




Ø 15 x 9,5mm



36



37



38



H2x2






Jx6



Ø 3,5x 14 mm





40


U x 2



U x 4



Ø4X12mm




41

T x 3



Ø4x25mm



42

U x 4



Ø 4x12mm

F x 1








L = 350 mm



G x 4



Ø 3 x 12 mm




43



44



Q x 1



Jx2



Ø3,5x 14 mm



45

S x 12



G x 12



Ø3X12mm

