



Only assembly required to add plastic legs

>Can be done with drill or screw driver

>Screw in 4 plastic legs in each corner